## Zenair Europe Service Letter



Thic S	arvica	Latter	(CT)	hoc	hoon	icenad	hw	7 anair	CARL	(Europe	(۵
1 1115 2	ervice	Letter		mas	peen	issueu	. DV	Lenair	SAKL	(Lurope	e).

S.L. Number:	ZE-2009-05								
Date of issue:	November 24, 2009								
Subject:	Aileron Bell-Crank stiffeners for the CH 601 XL/CH 650E.								
Affected Models:	All CH 601XL/CH 650E models built and operated as ULM (MTOM of 450 kg + 5%) as defined by LTF-UL standards (or similar).								
Serial Number(s)	All affected models								
Manufactured by:	Czech Aircraft Works (CZAW) and others.								
Purpose:	According to the <u>Institute for Reliability Engineering</u> at the <u>Technical University of Hamburg, Germany</u> , this modification has the potential to further reduce the possibility of non-linear vibrations in the aileron control system of the affected aircraft.								
	This upgrade includes one (1) extra channel per wing to support the aileron bell-crank attachment and additional "L" angles on the top and bottom wing skins as illustrated on the drawings (6Z-1G). See references for exact materials, dimensions, locations and installation details.  Parts include:  DESCRIPTION PART NUMBER QTY.  Bell-crank Support Channel 6Z-1G-1 2								
D:		Standard "L" Angle	6Z – 1G – 1	8					
<b>Directed Action(s):</b>		Inspection door covers	6Z – 1G – 3	2					
		A4 and A5 Rivets		As needed					
	Note: The wing skin does not need to be removed to install this upgrade, however, additional access/inspection holes need to be cut into the bottom wing surfaces to allow for installation of these parts.								
Effective date:	As soon as practicable.								
Compliance:	Zenair recommends compliance prior to disregarding the operating limitations outlined in German DAeC advisory number LTA08-011-1 (or similar).  Caution: Local conditions may vary - always comply with applicable regulations.								
	• Zenair Drawings No. 6Z-1G (Dec. 7)								
References:	Additional info in AMD S-LSA Service Manual for CH 601 XL*     * available free on the internet; call for more details.								

## Remarks:


Compliance with this Service Letter should be recorded in the aircraft's maintenance log.

Address inquiries concerning this Service Bulletin to your nearest Zenair representative or to:

Zenair Sarl Z.I. No.2 Aérodrome de Valenciennes 59121 PROUVY, France

Tel: 0033-(0)6-46-30-43-30 e-mail: Europe@zenair.com

www.zenairulm.com



**Page 2 of 2** Rev. 3.1